

Revisit

Tax Map No.

SURVEY FORM

Identification

Determination of Eligibility: Not Eligible

Property Description

Porch Width: Entrance bay only

Description /Significant Features:

Minimal Traditional. Windows on left bay are 2/2 dhs wood, right bay has 1/1 dhs vinyl. Frotn entry is covered by gable roof supported by wall brackets, concrete steps lead to entry. Right elevation side entrance.

Page 2

Alterations (including date(s), if known):

Partial Window replacement.

Architect(s)/Builder(s):

Historical Information

Historical Information:

Source(s) of Information:

Digital Photo ID(s)

File Name:

3904001

3904002

View:

Other:

Right oblique

Front elevation

Program Management

Recorded By:

Kristina Poston

Organization:

New South Associates

Date Recorded:

10/15/2018