

Statewide Survey of Historic Properties

State Historic Preservation Office
South Carolina Department of Archives and History
8301 Parklane Road
Columbia, SC 29223-4905 (803) 896-6100

Control Number: U /91/ 3839

Status County No. Site No.

Quadrangle Name: Rock Hill East

Tax Number: 6990000005

Intensive Survey Form

Identification

Historic Name: _____

Common Name: Unidentified House

Address/Location: 953 Church Road

City: _____ County: York

Vicinity of: Rock Hill, South Carolina

Ownership: Private State
 Corporate Federal
 City Unknown/Other
 County

Category: Building
 Site
 Structure
 Object

Historical Use: single dwelling commercial
 multi dwelling other

Current Use: single dwelling commercial
 multi dwelling other

SHPO National Register Determination of Eligibility:

Eligible Potentially Eligible
 Not Eligible Listed
 Contributes to Eligible District Determined Eligible/Owner Objection
 Contributes to Listed District Removed from NR

Other Designation: _____

Property Description

Construction Date: c 1900

Alteration Date: _____

Commercial Form: _____

Stories:

1 Story
 1 ½ Stories
 2 Stories
 2 ½ Stories
 3 Stories
 Other: _____

Construction Method:

Masonry
 Frame
 Log
 Steel
 Other: _____

Historic Core Shape:

Rectangular H
 Square Octagonal
 L Irregular
 T Other: _____
 U

Exterior Walls:

Weatherboard Tabby Asphalt roll
 Beaded Weatherboard Brick Synthetic siding
 Shiplap Brick Veneer Asbestos shingle
 Flushboard Stone Veneer Pigmented Structural Glass
 Wood Shingle Cast-Stone Other: _____
 Stucco Marble

Roof Features

Shape: Gable End

Materials: Metal

Foundation:

Not Visible Stuccoed Masonry Slab Construction
 Brick Pier Stone Pier Basement
 Brick Pier with Fill Stone Raised Basement
 Brick Concrete Block Other: _____

Porch Features

Width: Partial

Shape: Shed Roof

Significant Architectural Features: 1900 Central Hallway house type with a gable-end, standing-seam metal roof and an exterior chimney on the southeast elevation. The exterior walls are covered in rolled asphalt siding in a brick pattern. The windows were not visible. There is a partial width shed roof porch centered on the façade (northeast elevation).

South Carolina Statewide Survey of Historic Properties

Intensive Survey Form

Site No.: 3839

Alterations: The porch has been enclosed and there is a gable-el addition on the rear of the house and a one-room addition on the northwest elevation.

Architect(s)/Builder(s): _____

Historical Information

Historical Information: _____


Source of Information: _____

Photographs

Roll No. Neg. No. View of

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Use Grid for Sketching



Attach Photographs Here



Program Management

Recorded by: Terri DeLoach Gillett
New South Associates

Date Recorded: 5-29-2015