

Statewide Survey of Historic Properties

State Historic Preservation Office
South Carolina Department of Archives and History
8301 Parklane Road
Columbia, SC 29223-4905 (803) 896-6100

Site No. 1856 Status U Revisit
Quadrangle Name: Westville
Tax Map No. 062-00-00-035

SURVEY FORM

Identification

Historic Name: Store
Common Name:
Address/Location: 83 Sawmill Road
City: Kershaw ✓ Vicinity of County: Kershaw
Ownership: Private Category: Building Other:
Historical Use: Commercial
Current Use: Domestic
SHPO National Register Determination of Eligibility: Not Eligible

Property Description

Construction Date: circa 1940 Construction: Masonry Other:
Historic Core Shape: Rectangular Exterior Walls: Other Concrete block
Other: Foundation: Concrete block
Commercial Form: Other Roof Shape: Gable, lateral
Other: vernacular side-gable Roof Material: Composition shingle
Stories: 1 story Porch Shape: Shed
Other: Porch Width: Full façade

Description/Significant Features:

The front elevation has a central doorway, which consists of three wooden panels on the lower section and three horizontal window panes on the upper section; it is flanked by a one-over-one, double-hung, metal frame window on the eastern side and a large, single-pane window on the western side. A full-width, shed-roofed porch spans the façade and is supported by simple metal posts. The eastern elevation has a single, off-center door, similar to the front door, and a rectangular attic vent centered within the wooden siding in the gable end. The western elevation has two small, single pane windows with metal frames. A single, interior brick chimney is visible above the roof ridge.

Alterations (include date(s), if known):

Rear addition - post 1964; trailer addition - late 20th century

Architect(s)/Builder(s):

Historical Information

Historical Information:

No structure appears at this location on the 1938 USGS topographic map or the 1938 SCDOT map; aerial photographs from 1964 indicate that the main portion of the structure was standing at this time but the rear portions were added later. Based on the form and design of the main structure, as well as its location close to the road, it is possible that this building served as a store for the area. However, it appears to now function as a residence.

Source(s) of Information:

Historic maps and aerial photographs

Digital Photo ID(s)

File Name:

01856001

01856002

01856003

01856004

View:

Facing South

Facing Southwest

Facing Southeast

Facing Southeast

Other:

Program Management

Recorded by:

Heather L. Carpini

Organization:

S&ME, Inc.

Date Recorded:

03/16/2019